



# A smarter, safer approach to acid adjustment

See the eye-opening benefits of the Acid-Rite® 2500 Water pH Adjustment System

- Sodium bisulfate tablets
- Enhances chlorine efficacy in water
- Low odor
- Low maintenance
- Controllable adjustment
- NSF Standard 50 Certified


The Acid-Rite pH Adjustment System is a simple, safer and effective alternative to bulky liquid acid systems. Utilizing red Acid-Rite sodium bisulfate tablets, the feeder system fits easily into pump rooms making it a convenient and more manageable option for acid adjustment.

Call 1.800.245.2974 for a free consultation





# **Acid-Rite Water Adjustment System Installation and Specification**



### **Pool Size**

- Inside: 30,000-1,000,000 gallons
- Outside: 30,000- 350,000 gallons

## **Acid-Rite Unit Size**

- Footprint: 22" x 32"
- Flow Rate: 0-10 GPM
- Up to 8 lbs. / hr Sodium Bisulfate

### **Acid-Rite Tablets**

- · 99.97% Sodium Bisulfate
- 3-inch diameter
- · Red color for safety
- 45-lb pails

# No metering. No mixing. No contest.

Lightens the load on pool operators from safety, handling and maintenance, to creating a pleasant workplace environment. See for yourself.









	Safety	Handling	Maintenance	Material Compatibility and Corrosivity
CID ITE	Solid chemical made of sodium bisulfate with no dual containment	Easier to handle 45-lb reseable pails	Acid feeders rarely require cleaning or maintenance; no small tubing that can kink and crack	Tablets have low odor and are red in color to help eliminate inadvertent mixing of chemicals
atic Acid	Strong odor/ fuming; potential liquid spills	55-gal drums weigh more than 500 lbs	Feed pumps need frequent repair and tubing can leak	Strong corrosive liquid with strong noticeable odor; leaking tubes or feed pumps can attack equipment room
r Sodium ulfate	Bags are difficult to cut and empty; powder can accumulate on surfaces	50 lbs bags are awkward and difficult to handle, not resealable	Feed pumps need constant repair and tubes plug regularly; mixing motors fail	Powdered acid and leaking tubes can attack mixing motors and equipment



A Westlake Company 11 Stanwix Street Pittsburgh, PA 15222

Granulai

Acid Rite is a trademark of Axiall Ohio, Inc. 1022

800-245-2974 www.accu-tab.com

Call 1.800.245.2974 for a free consultation

